
replacing battery

INSTRUCTIONS FOR BATTERY PACK

The battery pack must be fully charged before the respirator is first used. Use only the P/N 10095165 battery charger from MSA. Other chargers can damage the battery due to internal wiring differences or incorrect charging rates.

A battery pack should be stored at a temperature range of 50°F to 85°F. If the battery pack has been stored in a “full charged” condition for more than one week, the battery pack should be charged until a full charge is indicated.

REPLACING THE BATTERY PACK

1. Remove the pack from the support belt.
2. Loosen the ring and pull the two connectors apart.
3. To re-install the battery pack, slip the battery pack on the support belt.
4. Line up the key on the battery cable plug with the slot in the female connector on the battery pack.
5. Push the plug into the female connector and turn the ring to secure it.

For More Information, call 1-800-MSA-2222 or Visit Our Website at www.MSAnet.com



MINE SAFETY APPLIANCES COMPANY
PITTSBURGH, PENNSYLVANIA, U.S.A. 15230