

7 December 2020

MSA Corporate Center

1000 Cranberry Woods Drive Cranberry Township, PA 16066 800.MSA.2222 www.MSAsafety.com

Discontinuation Notice

After many years of service, MSA and General Monitors are announcing the discontinuation of several General Monitors controllers effective 30 June 2021. While we understand that this may cause inconveniences for some customers, we offer our assurance that MSA and General Monitors' customers can continue to make use of the many remaining General Monitors and MSA controller solutions.

The following products are affected by this discontinuation:

- MC600 Multi-Channel Controller
- 580A Dual-Channel Combustible Gas Monitor
- DC110 Eight Channel Combustible Readout/Relay Module
- 2280A Four Channel H2S Gas Monitor
- DT210 Eight Channel H2S Readout/Relay Module
- 2602A Zero Two Series Control Module for H2S Applications
- FL802 Multi-Channel Flame Detection Readout/Relay Display Module
- MD002 Monitored Driver Output Module
- ZN002A Three Zone Control Module
- PS002 Power Supply

UITENONCOOL

Each product affected by discontinuation will continue to be supported with service and spare parts for a period of 5 years, or until critical components are exhausted.

Bill Fazenbaker

Product Line Manager, Flame Detection & Controllers